Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

OLIVIII IO/VIE OI OOIVIVEOITOIV	
	Page <u>1</u> of <u>1</u>
PATENT NO. : 7,059,152	· — —
APPLICATION NO.: 10/701,702	
ISSUE DATE : June13, 2006	
INVENTOR(S) : John Douglas OAKEY, Brian Morice DAVIES	
It is certified that an error appears or errors appear in the above-identified patent and is hereby corrected as shown below:	that said Letters Patent
In column 5, line 52, replace "moie" withmole	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Philip H. Von Neida, The BOC Group, Inc., Intellectual Property Dept. 575 Mountain Avenue, Murray Hill, NJ 07974

Attorney Docket: M02B131

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicants: John Douglas OAKEY, Brian Morice DAVIES

Title: Nitrogen Rejection Method and Apparatus

Commissioner for Patents

ATTN: Certificate of Correction Branch

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

A printing error has been discovered in the above-identified United States patent. A completed form for a Certificate of Correction which lists and corrects this error is enclosed herewith.

Inasmuch as the applicants submit that this error was introduced through no fault of the applicants, the applicants believe that no fee is due for the Certificate of Correction.

In the event a fee is due, kindly charge that fee to deposit account number <u>02-2865</u>.

Respectfully submitted,

/Philip H. Von Neida/

Correspondence Information Customer Number: 20411 Phone 908-771-6402 Fax: 908-771-6159 Philip H. Von Neida Registration No. 34,942 Attorney for Applicants Date: July 13, 2006